


























# FIG. 1



NAMES OF SPOTS	PROCESS			
	1 (2002.5.30)	2 (2002.6.15)	3 (2002.6.30)	4 (2002.7.15)
CONCRETE 1				
CONCRETE 2				
FRONTAL APPEARANCE				
REAR APPEARANCE				
GAS PIPE				
WATER PIPE				
1ST FLOOR INTERIOR				
2ND FLOOR INTERIOR				


**FIG.2**

# FIG.3



<IMAGE MANAGEMENT APPARATUS>

<DIGITAL CAMERA>



<IMAGE MANAGEMENT APPARATUS>

<DIGITAL CAMERA>




























FIG.4B

**FIG.5**



**PROCESS**

NAMES OF SPOTS	PROCESS			
	1 (2002.5.30)	2 (2002.6.15)	3 (2002.6.30)	4 (2002.7.15)
CONCRETE 1				
CONCRETE 2				
FRONTAL APPEARANCE				
REAR APPEARANCE				
GAS PIPE				
WATER PIPE				
1ST FLOOR INTERIOR				
2ND FLOOR INTERIOR				

**FIG.6**

FIG. 7

